

ECS Configuration Change Request

Page 1 of 1

Page(s)

1. Originator Willard Selph	2. Log Date: 8-3-99	3. CCR #: 99-0717	4. Rev: —	5. Tel: 301-883-4146	6. Rm #: 2107B	7. Org. SED
8. Title of Change: RAID for Ingest for NSIDC						
9. Originator Signature/Date <i>Willard Selph</i> 8-3-99		10. Class II	11. Type: CCR	12. Need Date: 08/03/99		
13. Office Manager Signature/Date <i>James R. [Signature]</i> 8-3-99		14. Category of Change: Initial Baseline		15. Priority: (If "Emergency" fill in Block 28). Emergency		
16. Documentation/Drawings Impacted: 920-TDN-001 Rev05, 920-TDG-001Rev08		17. Schedule Impact:		18. CI(s) Affected: g0drg01, protegy2		
19. Release Affected: N/A		20. Date due to Customer: 08/03/99		21. Impl. Date: 08/03/99		22. Estimated Cost: None
23. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input checked="" type="checkbox"/> Other:						
24. Description of Change: (use additional Sheets if necessary) Building the RAID for Ingest at NSIDC here at Landover and sending to NSIDC. <i>Documents will be updated when all the work is complete</i>						
25. Proposed Solution: (use additional sheets if necessary) Remove 17 x 9 GB drives from g0drg02 from the RAID enclosure EIN 1683 and bring to Landover. Install drives into Protegy 2 RAID enclosure EIN 1195 and build the Ingest RAID for NSIDC. Remove entire RAID enclosure from Protegy 2 and send to NSIDC. When the new 17 x 18 GB drive arrives the drives will be replaced at GSFC and the RAID enclosure will be replaced on Protegy 2.						
26. Alternate Solution: (use additional sheets if necessary) Wait for the RAID enclosure to be delivered.						
27. Consequences if Change(s) are not approved: (use additional sheets if necessary) The Ingest machine will not be operational at the time of End-to-End testing.						
28. Justification for Emergency (If Block 15 is "Emergency"): This is needed to be completed for NSIDC to begin End-to-End testing.						
29. Site(s) Affected: <input type="checkbox"/> EDF <input type="checkbox"/> Mini-DAAC <input type="checkbox"/> VATC <input type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input checked="" type="checkbox"/> Other ECS test machine						
30. Board Comments:				31. Work Assigned To:		
32. EDF/REL2 CCB Chair (Sign/Date):		33. Disposition: <input type="checkbox"/> Approved <input type="checkbox"/> A/C <input type="checkbox"/> Disapproved <input type="checkbox"/> Fwd/ECS <input type="checkbox"/> Fwd/ESDIS		34. (TBD)		
35. M&O CCB Chair (Sign/Date): <i>James R. [Signature]</i> 8/3/99		36. Disposition: <input checked="" type="checkbox"/> Approved <input type="checkbox"/> A/C <input type="checkbox"/> Disapproved <input type="checkbox"/> Fwd/ECS <input type="checkbox"/> Fwd/ESDIS		37. CM Manager's Closure:		
38. ECS CCB Chair (Sign/Date):		39. Disposition: <input type="checkbox"/> Approved <input type="checkbox"/> A/C <input type="checkbox"/> Disapproved		40. CCR Closed Date:		

CM01 March 8, 1999
CCB

ECS/EDF/REL2

08-03-99A09:01 0077

ORIGINAL